T.T. 183 LLC Phone # 225-473-8222

Pipeline Test Letter

Date: 11-14-24

To Whom it may concern:

The cargo piping and relief valve as required by 3 CFR156.170, on Tank Barge # _FmT 5052 was located at TT 183, LLC, was tested on 11-14-24 at 188 psi.

- Pressure gauge was found to be operating.
- The relief valve functioned as required.
- The steam piping system as tested at ______psi.
 The steam relief valve functioned as required.

T.T. Barge Cleaning Mile 183, Inc.

MARINE VESSELS VAPOR TIGHTNESS DOCUMENTATION

REQUIRED SUBPART BB – NATIONAL EMISSION STANDARDS FOR BENZENE EMISSIONS FROM BENZENE TRANSFER OPERATIONS SECTION 61.300-61.306

1.	Test Method Conducted: <u>Dry air/soap</u>	
2.	Marine Vessel Owner: FM T Address: 2360 Fifth Street Mandeville, La 10471	
3.	Marine Vessel Identification Number: FMT 5052	
4.	Testing Location: TT Barge Mile 183	
	Date: 11-14-24	
6.	. Tester Name: Agran Jackson Company: TT 183 LLC	
7.	Signature of Tester: Than faction	
8.	Witnessing Inspector:	
9.	Witnessing Inspector Signature:	
TEST RESULTS: Test cargo tanks and related vapor system to 16 oz.		
Beginning pressure 16 oz. at 12:00 time. Barge pass OK		
Ending pressure 10 oz. at 12.30 time.		
Pressure cargo tanks and pipelines to 1.0 psig dry air record pressure allow vessel to remain pressurized for thirty minutes and use soap test to inspect for leaks. At the end of thirty minutes record pressure reading.		
	3.20 ounces per square inch	30,000 bbl10 psig 1.6 ounces per square inch 2.70 inches of water

If pressure change is greater than the above limit, vessel cannot be certified. The source of the leak must be identified and repaired and the vessel retested.